



## **Service Letter No. EX2**

**August, 1993**

### **Subject: Model EXB59 Solenoid Valve Installation**

On page 5 of the Model EXB59 Installation Manual under "Important Guidelines", the paragraph which starts with, "Install the solenoid valve, . . ." should be replaced with the following paragraph:

Install the solenoid valve, P/N 019304, on the chassis rail using existing predrilled holes. If no suitable location is available on the chassis rail, then mount the solenoid valve to the body sheet metal. Avoid excessive heat coming from the exhaust system. The distance from the solenoid valve to the air cylinder of the Extarder should be within or less than the length of the supplied hose, P/N 018916.

The initial shipment of the Model EXB59 aftermarket kits, P/N 019426, along with the informational packet mailed on August 19, 1993, contain manuals with this error. Please correct any manuals found to contain this error. Corrected manuals will have the P/N 019744B.

**SERVICE LETTER**